


Noha[®]
the invisible handle



NS 105
INSTALLATION GUIDE

START WITH THE MILLING

1



2




IMPORTANT: Take care that the dimensions are accurate


CONTINU WITH THE INSTALLATION




1




2




3




4





5



6



7



8

