



**Noha**<sup>®</sup>  
the invisible handle






INSTALLATION GUIDE  
NS 200

## START WITH THE MILLING

1




2



a	d	c
38 mm	32 mm	3 mm
39 mm	33 mm	3 mm
40 mm	33 mm	3.5 mm
41 mm	33 mm	4 mm
42 mm	33 mm	4.5 mm

IMPORTANT: Take care that the dimensions are accurate


# CONTINU WITH THE INSTALLATION




1




2




3




4




5




6




7




8




9



10



11



12

